


FIG. 1










FIG. 3A**FIG. 3B****FIG. 3C****FIG. 3D****FIG. 3E****FIG. 3F**

FIG. 4









FIG. 5A**FIG. 5B****FIG. 5C****FIG. 5D****FIG. 5E**






FIG. 7




FIG. 8




FIG. 9A




FIG. 9B




FIG. 10




FIG. 11




FIG. 12

URL <http://www.maintain.co.jp/db/input.html>

TROUBLE DB INPUT WINDOW

OCCURRENCE DATE 2000/3/15 ~ 4040

TYPE OF APPARATUS **** ~ 4010

SUBJECT OPERATION ERROR (START-UP ERROR) ~ 4030

SERIAL NUMBER S/N 465NS4580001 ~ 4020

DEGREE OF URGENCY D ~ 4050

SYMPTOM LED IS KEPT FLICKERING AFTER POWER-ON
 ↗ 4060
 ↘

REMEDY POWER ON AGAIN (PRESS RED BUTTON IN ACTIVATION)
 ↗ 4070
 ↘

PROGRESS INTERIM HAS BEEN DONE
 ↗ 4080
 ↘

(SEND) 4100 (RESET) 4110 4120

LINK TO RESULT LIST DATABASE SOFTWARE LIBRARY OPERATING GUIDE

FIG. 13




FIG. 14

